

Chemetall Oakite

10149

MATERIAL SAFETY DATA SHEET

PRODUCT CODE: 10149
OAKITE GARDOCOOL C 9126
200-217-007

HMIS 1 0 0 C

=====

SECTION I - PRODUCT IDENTIFICATION

=====

TRADE NAME	OAKITE GARDOCOOL C 9126	EMERGENCY TELEPHONE NUMBER:
CHEMICAL NAME		(800) 424-9300 (CHEMTREC)
AND SYNONYMS	NA-Mixture	
MANUFACTURER'S NAME	OAKITE PRODUCTS INC. (908) 464-6900 (8am-5pm)	
AND TELEPHONE NO.	A Member of The CHEMETALL Group	
ADDRESS	50 Valley Road Berkeley Heights NJ 07922	
DATE OF PREPARATION	11-08-2001	

=====

SECTION II - HAZARDOUS INGREDIENTS

=====

	CAS NO.	% BY WT	ACGIH OSHA		UNITS
			TLV (TWA)	PEL (TWA)	
Diglycolamine	0000929066	1-5	NE	NE	
Phosphate ester	0039464692	1-10	NE	NE	
Non-hazardous ingredients		Bal.			

Unidentified ingredients are considered not hazardous under Federal Hazard Communication Standard (29CFR 1910.1200).

All components of this material are on the US TSCA Inventory.

CARCINOGENICITY: No substance in this product is listed by IARC, NTP, or regulated by OSHA as a carcinogen.

=====

SECTION III - PHYSICAL DATA

=====

BOILING POINT (F)	NE	SPECIFIC GRAVITY (H2O=1)	1.012
VAPOR PRESSURE (mm Hg)	NE	Bulk Density	8.43 lbs/gal
VAPOR DENSITY (Air=1)	NE	PERCENT VOLATILE	
SOLUBILITY IN WATER	Complete	BY WEIGHT(%) Excludes H2O	0
EVAPORATION RATE (Water=1)	1	PH	

Oakite Products, Inc. warrants that the product or products described herein will conform with its published specifications. The products supplied by Oakite and information related to them are intended for use by buyer's manufacturing industrial and/or laboratory. Buyer should undertake suitable verification and testing to determine the suitability of the Oakite materials for their own particular purpose. Buyer's reliance on use of products are beyond Oakite's intent. Oakite does not warrant any representation and information for the use of such products. OAKITE DISCLAIMS ALL OTHER WARRANTIES INCLUDING THE IMPLIED WARRANTY OF MERCHANTABILITY AND FITNESS FOR ANY PARTICULAR PURPOSE IN CONNECTION WITH THE USE OF ITS PRODUCTS.

NA - Not Applicable

NE - Not Established

10149

APPEARANCE AND ODOR	Light amber liquid; bland odor.	PH (concentrate)	9-10
---------------------	---------------------------------	------------------	------

SECTION IV - FIRE AND EXPLOSION HAZARD DATA

FLASH POINT (Method Used): None
FLAMMABLE LIMITS: LEL: NA UEL: NA
EXTINGUISHING MEDIA: Carbon dioxide, dry chemical, or foam.
SPECIAL FIRE FIGHTING PROCEDURES: Wear Self-Contained Breathing Apparatus (SCBA).
UNUSUAL FIRE AND EXPLOSION HAZARDS: See Section VII. (HEMIS)
See Section VI. (U.S.)

SECTION V - TOXICOLOGICAL PROPERTIES/HEALTH HAZARD INFOR-

ROUTE(S) OF ENTRY:

INHALATION:	SKIN:	DIGESTION:
X	X	X

MEDICAL CONDITIONS AGGRAVATED BY EXPOSURE: None known

SYMPTOMS/EFFECTS OF OVEREXPOSURE:

Prolonged exposure to high mist concentrations may cause irritation of mucous membranes. If material is heated, the vapors/fumes may cause respiratory irritation. Direct contact with skin may cause irritation. Direct contact with eyes causes irritation.

FIRST AID

EYES: Immediately flush eyes with large amounts of water for at least 15 minutes while holding eyelids open. Get medical attention.

SKIN: Wash affected area with large amounts of water. If irritation develops, get medical attention.

INGESTION: Contact local poison control center or physician IMMEDIATELY!

INHALATION: Move victim to fresh air.

SECTION VI - FIRST AID

NA - Not Applicable

NE - Not Established

Chemetall Oakite

10149

MATERIAL SAFETY DATA SHEET

STABILITY: NORMALLY STABLE
INCOMPATIBLE MATERIALS: Strong acids, Strong oxidizers.
HAZARDOUS DECOMPOSITION PRODUCTS: Combustion may produce Carbon monoxide,
Carbon dioxide. Phosphorous oxides,
Nitrogen oxides, Boron oxides.

=====

SECTION VII - REACTIVITY DATA

=====

SPILL OR LEAK PROCEDURES: Wear personal protective equipment (See Section VIII).

Clean up with absorbant material. Store in dry container for disposal. Flush area with plenty of water.

WASTE DISPOSAL METHOD: Dispose of in accordance with Local State and Federal regulations.

=====

SECTION VIII - PREVENTATIVE MEASURES

=====

RESPIRATORY: Respirator not normally required. For symptoms of overexposure, wear a NIOSH-approved dust/mist respirator.

EYEWEAR: Wear chemical safety goggles.

CLOTHING/GLOVES: Wear chemical-resistant gloves and clothing as needed to prevent skin contact.

VENTILATION: Local exhaust may be necessary for some handling/use conditions. Specific needs should be addressed by supervisory or health/safety personnel.

=====

SECTION IX - STORAGE REQUIREMENTS/ADDITIONAL INFORMATION

=====

Store in closed container.

APPROVAL

NAME

Michael Chang

Mgr. Health & Environmental Dept.

TITLE

11/08/2001

DATE OF PRINTING

NA - Not Applicable

-3-

NE - Not Established